

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-4124	DATE	December 01, 2025
MANUFACTURER	KTM AG (Japanese Importer : KTM Japan KK)		
DESCRIPTION OF DEFECT	Due to material deviations, small cracks may occur on the fuel filler cap seals. This can lead to the possibility of fuel leaking from the fuel cap, which could lead to ignition and fire in the worst case. For this reason, the fuel filler cap seals on all affected vehicles must be replaced with the improved version.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
8BL-390DUKE963	390DUKE	2024	403 UNITS
8BL-990DUKE	990DUKE	2024	120 UNITS
250DUKE	250DUKE	2024	102 UNITS
8BL-401HQV963	Vitpilen401	2024	113 UNITS
8BL-401HQV963	Svartpilen401	2024	233 UNITS
250JUE40	Svartpilen250	2024	100 UNITS
TOTAL			1,071 UNITS