

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	GAI-4143	DATE	2026/1/26
MANUFACTURER	Massey Ferguson (Japanese Importer :MSK Farm Machinery Corporation CEO Takahata Toshinobu)		
DESCRIPTION OF DEFECT	<p>On tractors with a suspended front axle, the 4WD shaft cover may develop fatigue cracks at the mounting points due to insufficient design review. If continually used, the cover may lose its retention, leading to detachment. In the worst case, it can hinder other traffic. For all units, we will install a reinforcement bracket. If cracks are found at the mounting points, we will replace the 4WD shaft cover with the improved design.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDR-SU44A5S	MF5S145	2022-2025	63
YDR-SU44A5S	MF5S125	2022-2025	30
		TOTAL	93