

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-4147	DATE	26 th Feb, 2026
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>In case of faulty signals of the torque sensor, the software might lead to unintentional steering movement of the vehicle.</p> <p>If the failure is not correctly detected due to software weakness, an unintentional steering movement of the vehicle cannot be ruled out and causes the steering vibrations.</p> <p>If a failure of the software is detected by the steering gear system correctly, the driver is alerted by a check control message "Limited steering assistance", a minimal change in steering feel while driving and limited steering support in standstill.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-32GP20	BMW X3 20 xDrive	2024-2025	15
3CA-12GR20	BMW X3 20d xDrive	2024-2025	537
3AA-72GP30	BMW X3 M50 xDrive	2024-2025	188
		Total	740