

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	Gai-4155	DATE	25.02.2026
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	During repeated engine starts and in start-stop operation, the contacts experience abnormal wear, and wear particles may accumulate beneath the lower contact point. Over the service life of the starter, this impairs the engine's starting capability. Under certain circumstances, it may no longer be possible to start the engine. In the worst-case scenario, there is a risk of fire either when activating the starter or while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-12CM20	「BMW 220i」	2021-2022	365
3BA-5F20	「BMW 318i」	2020-2022	2,023
3BA-6K20	「BMW 318i Touring」	2020-2022	1,152
3BA-5F20	「BMW 320i」	2020-2022	1,232
3BA-6K20	「BMW 320i Touring」	2020-2022	640
3DA-5V20	「BMW 320d xDrive」	2020-2023	2,736
3DA-6L20	「BMW 320d xDrive Touring」	2022-2023	387
	「BMW 320d xDrive Tr.」	2020-2022	2,749
3BA-5F20	「BMW 330i」	2020-2021	125
3BA-12AP20	「BMW 420i Coupe」	2020-2022	1,603
	「BMW 420i Cabriolet」	2020-2022	472
3BA-12AV20	「BMW 420i Gran Coupe」	2021-2022	1,242
3DA-32AX20	「BMW 420d xDrive Gran Coupe」	2022	404

3BA-JR20S	「BMW 523i」	2020-2022	236
3DA-JF20	「BMW 523d xDrive」	2020-2022	995
3DA-JP20	「BMW 523d xDrive Touring」	2020-2022	351
3BA-JT20T	「BMW 530i Touring」	2022	23
3BA-TY20	「BMW X3 xDrive20i」	2020-2022	219
3DA-UZ20	「BMW X3 xDrive20d」	2020-2024	4,466
3DA-VJ20	「BMW X4 xDrive20d」	2020-2023	1,665
3BA-2V20	「BMW X4 xDrive30i」	2021-2022	159
3BA-HF20	「BMW Z4 sDrive 20i」	2020-2022	406
		TOTAL	23,650