

Form No. 4: Summary of Recall in English (Related to Article 2)**Vehicle Safety/Pollution Recall in Japan**

Import Vehicles

Campaign No.	Gai-4157	Date	Feb. 24, 2026
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	It is possible that moisture has entered the Transmission Control Module during the assembly process. Under certain conditions there is a risk that this moisture may result in non-illumination of indicating the selected gear. Replace the Transmission Control Module.		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-L123WB	Range Rover Sport	2025	2
		Total	2

(JIS A4 size)