

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic, Import Vehicles

CAMPAIGN No.	Gai - 4134	DATE	February 12, 2026
MANUFACTURE	BYD Company Limited (Japanese Importer : BYD Auto Japan Inc.)		
DESCRIPTION OF DEFECT	Inside the rear light-firearm, the desiccant interferes with the circuit board, causing a short circuit or disconnection. As a result, direction indicators may show symptoms of fast flashing or intermittent lighting and non-lighting.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BYD	ATTO 3	2022 - 2023	1097
		TOTAL	1097