

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-4169	DATE	30.03.2026
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	On affected vehicles an incorrect firmware version of the LED drivers was installed, which could lead to a failure of various rear light functions (brake lights, direction indicator, taillight). The fault will be displayed by a check-control message. When the vehicle is restarted, the fault is usually no longer present but may occur again later.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-82GE15	「BMW 120」	2025	205
	「BMW 220 Gran Coupe」	2025	23
3CA-22GF20	「BMW 120d」	2025	121
	「BMW 220d Gran Coupe」	2025	35
3BA-22GE20	「BMW M135 xDrive」	2025	37
	「M235 xDRIVE Gran Coupe」	2025	7
		TOTAL	428