

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-4167	DATE	March 26, 2026	
MANUFACTURER	Volvo Truck Corporation (Japanese Importer : UD Trucks Corporation)			
DESCRIPTION OF DEFECT	With regards to the Front Axle Steering Control Unit, due to insufficient design examination of the Lane Keeping Assist function, the steering vibration of the Lane Departure Warning may become smaller when the Lane Keeping Assist system is operating. As a result, lane departure may not be properly detected through the steering vibration warning, which may lead to non-compliance with the Japan safety regulations.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2DG-5S4TCA1	FH	2024	1	
		TOTAL	1	