

TIRE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Tires

CAMPAIGN No	Sou-20		DATE	13th Mar. 2026
MANUFACTURER	Sumitomo Rubber Industries, Ltd.			
DESCRIPTION OF DEFECT	Due to inadequate control of equipment in the manufacturing process of studless tires used on large trucks and buses, some tires may have insufficient rubber adhesion to the steel materials placed in the sidewall area, resulting in reduced rubber thickness inner surface of the tire. As a consequence, the sidewall may become damaged (such as bulging or cracking) during operation, causing air leakage and, in the worst case, a risk of tire burst.			
COMMERCIAL NAME	TYPE	CLASSIFICATION	MODEL YEAR RECALLED	NUMBER OF ITEMS
DUNLOP SP062	265/70R19.5 140/138J SP062	For Truck & Bus	Code : 1XMW 1624 Serial : TQ196144~TQ196164 Date : 27th Apr. 2024~28th Apr. 2024	21pcs
			Code : 1XMW 1624 Serial : TQ196166~TQ196180 Date : 27th Apr. 2024~28th Apr. 2024	15pcs
			Code : 1XMW 2024 or 2124 Date : 19th May 2024~1st Jun. 2024	203pcs
			TOTAL	239pcs