

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	GAI-4190	DATE	May, 25, 2026
MANUFACTURE	Aston Martin Lagonda Limited (Japanese Importer : Aston Martin Japan Limited)		
DESCRIPTION OF DEFECT	Aston Martin has determined that a defect which relates to motor vehicle safety may exist for certain DBX vehicles that were manufactured from February 27 2020 and November 5 2025. On affected vehicles, a reduced diameter shank bolt can cause the pin for the torque reaction link to move within the joint causing excessive wear and potential early failure. A failure of the rear lower suspension arm can affect vehicle handling or cause damage to other suspension components and the rear brakes. The failures can increase the risk of a crash. On the affected vehicles it is necessary to inspect the lower suspension arm for damage and to replace the bolts for the rear torque reaction links.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
7BA-AM801	DBX	2021-2024	535
7BA-AM801	DBX707	2023-2025	470
Unknown	DBX707	2025	31
Unknown	DBXS	2026	1
		TOTAL	1037