

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-4148	DATE	May 21 st 2026
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	A replacement part (steering wheel with Takata airbag, or the airbag inflator itself) relevant to former recalls may possibly have been installed, since they are compatible with the originally installed parts. It cannot be ruled out that, in case the airbag is activated during a crash, the inflator ruptures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-DS25	BMW 525i Touring	2003	16
GH-DS30	BMW 530i Touring	2003	3
		TOTAL	19