

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ / Import Vehicles

CAMPAIGN No.	GAI-4183	DATE	May 21, 2026
MANUFACTURE	SCANIA CV AB (Japanese Importer: SCANIA JAPANA Co. Ltd.)		
DESCRIPTION OF DEFECT	For the air pressure control system (APS), (1) The material of the seal of the APS ventilating valve is inappropriate, consequently the seal could be softened due to oil contamination and airtight of air pressure may not be retained. (2) Sealing effect of the valve could be hampered and airtight may not be retained on account of frozen moisture in the compressed air when the ambient temperature is low due to inappropriate control program. Therefore, air leakage occurs accompanied by warning lamp displayed and emergency brake is applied due to dropped system air pressure if the vehicle is continued to be used. Or, air pressure does not rise after starting the engine and the parking brake cannot be released then vehicle may be immobilized.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SCANIA	LPGRS series Truck	2017 - 2024	1,609
		TOTAL	1,609