

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4188	DATE	May 21, 2026
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	Due to fluctuations in the manufacturing process which could cause the locking function of the seat belts to be restricted after they are tightened. In the event of an accident where the driver and/or front passenger seat belt pretensioner activates, the seat belt may not maintain proper tension, resulting in increased belt slack and reduced restraint performance. As a result, the occupant may not be adequately restrained.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3AA-GU20S	Audi Q5 TFSIq	2025	23
3AA-GUSA	Audi SQ5 Air-suspension	2025	25
3AA-GUSS	Audi SQ5	2025	1
3CA-GU20	Audi Q5 TDIq	2025	90
		Total	139