

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4182	DATE	May 14, 2026
MANUFACTURER	Audi (Japanese Importer: VOLKSWAGEN Group Japan K.K.)		
DESCRIPTION OF DEFECT	Due to a malfunction in the manufacturing system, the bolted connection for the push rod between the brake pedal and brake servo may not be secured according to requirements. This may lead to the connection coming loose. If the connection comes completely loose, in the worst case, there is a risk that it will no longer be possible to brake the vehicle using the brake pedal.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-GEEAS	Audi e-tron	2020-2023	225
ZAA-GEEASB	Audi e-tron 50	2021-2023	89
ZAA-GEEAV	Audi e-tron S	2022-2023	35
	Audi SQ8 e-tron	2024	16
ZAA-GEEDE	Audi Q8 e-tron	2024	304
		Total	669