

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No .	Gai-4206	DATE	June. 26. 2026
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	the fuel pump sealing may not have been assembled correctly at the factory. As a consequence, minimal amounts of fuel may seep from the pump and may be perceived as smell or – in isolated cases – as discoloration on adjacent parts.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-R137A	「 BMW R1300GS 」	2023 - 2026	1,927
8BL-R137A	「 BMW R1300GSA 」	2024 - 2025	1,381
8BL-S10AC	「 BMW S1000RR 」	2024 - 2025	684
8BL-S10AC	「 BMW S1000R 」	2025 - 2025	244
8BL-S10AC	「 BMW M1000RR 」	2025 - 2025	127
8BL-S10AC	「 BMW M1000R 」	2025 - 2025	258
		TOTAL	4,621