

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-4163	DATE	June 22 2026
MANUFACTURE	Hyundai Motor Company (Japanese Importer : Hyundai Mobility Japan Ltd.)		
DESCRIPTION OF DEFECT	In certain vehicles equipped with auxiliary seats, the stopper installed on the rail of the side sliding window is improperly positioned, creating a potential risk that passengers may be unable to evacuate in the event of an emergency.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ADG-RD00	Hyundai PY	2009 – 2010	40
LDG-RD00	Hyundai PY	2011 – 2017	196
2DG-RD00	Hyundai PY	2017-2025	55
		TOTAL	291