

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai - 4187	DATE	June 19, 2026
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	In the braking system, the design of the rear brake hose retainer and the heat-shield tube is inadequate, resulting in insufficient heat-shielding performance. Consequently, radiant heat emitted from the exhaust pipe located near the brake hose during riding may damage the surface of the brake hose. If used in this condition, brake fluid may leak, and in the worst case, there is a risk that the rear brake may fail to operate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-5D00	Panigale V4 Panigale V4 S Panigale V4 Tricolore Panigale V4 Tricolore Italia	2025-2026	343
8BL-7F00	Streetfighter V4 Streetfighter V4 S	2025-2026	131
		TOTAL	474