

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic(Import) Vehicles

CAMPAIGN No.	Gai - 4199	DATE	June 19, 2026
MANUFACTURER	DUCATI MOTOR HOLDING SpA (Japanese Importer: DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	In the braking system, insufficient design consideration of the pivot pin that connects the rear brake pedal and the push rod may cause the pin to rust. As a result, continued use in this condition can make the rear brake pedal movement sluggish and, in the worst case, may lead to brake drag.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
8BL-5D00	Panigale V4	2025-2026	295
	Panigale V4 S		
		TOTAL	295