

Form No. 4: Summary of Recall in English (Related to Article 2)**Vehicle Safety/Pollution Recall in Japan**

Import Vehicles

Campaign No.	Gai-4171	Date	June 9, 2026
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The third-row lower seatbelt anchorage bracket may contain a weld stud of insufficient ISO strength, due to material contamination at the supplier. An insufficiently strong weld stud in this position could result in the safety restraint system not functioning correctly in the event of a crash, increasing the risk of occupant injury. Replacing the seatbelt anchorage bracket.		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-LE72WAB	DEFENDER 110 / DEFENDER 130	2026	69
7BA-LE72XAB	DEFENDER 110		14
		Total	83

(JIS A4 size)