

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic~~Import~~ Vehicles

CAMPAIGN No.	Gai-4213	DATE	30.07.2026
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	During repeated engine starts and in start-stop operation, the contacts experience abnormal wear, and wear particles may accumulate beneath the lower contact point. Over the service life of the starter, this impairs the engine's starting capability. Under certain circumstances, it may no longer be possible to start the engine. In the worst-case scenario, there is a risk of fire either when activating the starter or while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-6K20	「BMW 320i Touring」	2022	1
3DA-5V20	「BMW 320d xDrive」	2024	1
		TOTAL	2