

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-4216	DATE	July. 30. 2026
MANUFACTURER	HONDA AUTOMOBILE(THAILAND)CO., LTD. HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	In some driver's seats or front passenger's seats, the ends of their left side frames are not correctly molded due to the inappropriate mold to form those frames and inappropriate manufacture management. For this reason, the shapes of the ends of those frames do not comply with the Safety Regulations.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-CY2	「ACCORD」	2025	1,143
TOTAL			1,143