

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-4217	DATE	July. 30. 2026
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	the control unit of the reverser due to defective sealing of the control unit. This moisture can lead to corrosion of electrical contacts inside the control unit over time. Corrosion can lead to malfunction of the control unit (failure of the reverser comfort function).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-K16AA	「BMW K1600GT」	2016 – 2021	206
2BL-K16AA	「BMW K1600GTL」	2017 – 2021	165
2BL-K16AA	「BMW K1600B」	2017 – 2020	396
8BL-K16AA	「BMW K1600GT」	2021 – 2024	111
8BL-K16AA	「BMW K1600GTL」	2021 – 2024	121
8BL-K16AA	「BMW K1600B」	2021 – 2023	35
		TOTAL	1,034