

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	R-4212	DATE	2026/7/28
MANUFACTURE	Hyundai Motor Company (Japanese Importer : Hyundai Mobility Japan Co., Ltd)		
DESCRIPTION OF DEFECT	Due to insufficient design of the 3-way valve in the motor cooling system: ① Excessive stress may be applied to the drive shaft—an internal component of the valve—causing damage. ② The circuit protection fuse has a large capacity, which can lead to the circuit not being properly shut off in the event of a short circuit, causing abnormal overheating. Therefore, if coolant leaks from a damaged drive shaft and enters the motor control unit, it will be heated by the overheating electrical circuit, generating steam. If use continues in this state, the motor's output will be limited, and in the worst case, the vehicle may become unable to move. * 3-way valve: A valve that switches the coolant flow path within the motor cooling system.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-B1511	INSTER	2025, 2026	809
		TOTAL	809