

Form No. 4: Summary of Recall in English (Related to Article 2)**Vehicle Safety/Pollution Recall in Japan**

Import Vehicles

Campaign No.	Gai-4218	Date	July 28, 2026
Manufacturer	Jaguar Land Rover Limited Japanese Importer: Jaguar Land Rover Japan Limited		
Description of defect	The fuel tank wall thickness may be below design specification in the part of area. A fuel tank with a thinner-than-designed wall may not perform adequately in the event of a crash, leading to an increased risk of fuel spillage and potentially fire.. Replace the Fuel Tank.		

Type	Commercial name	Model year recalled	Number of vehicles
3CA-LE72WAB	DEFENDER 110	2026	3
3CA-LE72WCB			1
		Total	4