

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5162	DATE	Jun.3.2022
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In PDA* of a driving support system, due to an improper control program when the brake pedal is operated during deceleration controlled by the PDA, the braking force may remain engaged even after the end of PDA control. In this condition, poor acceleration occurs, and if the vehicle is continuously operated in this condition, it may produce smoking due to overheating of the brakes, in the worst case, vehicle fire could occur.</p> <p>*Proactive Driving Assist: A system that assists in vehicle deceleration and steering depending on the surrounding circumstances and the driving conditions</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6AA-ZWR90W	[NOAH] [VOXY]	2021-2022	15,590
6AA-ZWR92W			74
6AA-ZWR95W			3,120
		TOTAL	18,784