

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5163	DATE	June.6.2022
MANUFACTURER	Kodaira industry corporation		
DESCRIPTION OF DEFECT	In the stainless steel hinge attached to the upper part of the rear pillar of the large dump truck, the welding range of the hinge part is inappropriate, so that the strength of the mounting part is insufficient. Therefore, if it is continued to be used as it is, cracks occur in the weld part due to vibration and stress at the time of opening and closing, and in the worst case, the welding part breaks and the hinge part and the upper frame part may fall off and be injured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
HINO	PROFIA	2012~2020	4
Mitsubishi Fuso	Super Great	2019	1
TOTAL			5

(日本工業規格A列4番)