VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5167	DATE	JUN-27-2022	
MANUFACTURER	YAMABIKO CORPORATION President & C.E.O. Hiroshi Kubo			
SUMMARY OF DEFECT	The retaining ring was not attached to the gear part of the axle of the agricultural chemical sprayer vehicle, as a result, the gears may not mesh properly, and vibration and abnormal noise may occur. If the agricultural chemical sprayer vehicle is continued to be used without the retaining ring, the gear may prematurely wear, and in the worst case, the vehicle may not be able to run or brake.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
YDN-S1091A	SSV1091FSC/A	2021	
	SSV1091FSC/LA	2021	29
	SSV1091FSC/TA	2021	
YDN-S1091B	SSV1091FS/A	2021	4
		TOTAL	33