

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5179	DATE	Jul.5 2022
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>On some heavy-duty touring buses, the programming of the electrical component control ECU is inappropriate, so</p> <p>① The parking brake status may not be correctly displayed when the parking brake is released. In addition, stop lights, side turn signal lights, license plate lights, EZGO (hill start assist system), hill-holder, etc. may not function.</p> <p>② When the seat belt is not fastened, the “Fasten your seat belt” pop up message may not appear.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2TG-MS06GP	「FUSO AERO ACE」	2017～2021	1,973
	「FUSO AERO QUEEN」	2017～2021	332
		TOTAL	2,305