

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5176	DATE	July 13. 2022
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In the damper disc of an agricultural tractor, the setting of the spring in the damper disc is improper in the low engine speed range, so the spring may resonate, the tooth surface in the damper disc may be hit, and the tooth surface may be worn. Therefore, if the tooth surface is continued to be used as it is, the tooth surface may be worn out, and in the worst case, the tooth surface may not be able to run.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
—	「YT328A」	2020~2022	98	
—	「YT330(J)」	2016~2019	927	
	「YA330A(J)」	2019~2022	399	
—	「YT333(J)」	2016~2019	1794	
		2016~2019	261	
	「YT333A(J)」	2019~2022	1891	
		2019~2022	193	
—	「YT333R(J)」	2022	2	
		2022	1	
TOTAL			5,566	