

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5184	D A T E	July. 21. 2022
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	In the harness connector of the electric parking brake, the selection of the resin material is inappropriate, so the connector may crack due to such influence of snow melting agent. Therefore, there is a possibility that the harness connector will be disconnected due to vehicle vibration, then the warning light will be turned on, and the electric parking brake will not operate or cannot be released.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-VM4	「Levorg」	2014~2017	83,053
DBA-VMG		2014~2017	19,916
DBA-GK2	「Impreza」	2016~2017	1,408
DBA-GK3		2016~2017	1,151
DBA-GK6		2016~2017	2,812
DBA-GK7		2016~2017	5,055
DBA-GT2		2016~2017	8,174
DBA-GT3		2016~2017	5,135
DBA-GT6		2016~2017	9,080
DBA-GT7		2016~2017	15,777
DBA-GT3	「XV」	2017~2018	10,953
DBA-GT7		2017~2018	30,607

DBA-VAG	「WRX」	2014~2016	15,417
DBA-BN9	「Legacy」	2014~2017	9,438
DBA-BS9		2014~2017	29,407
TOTAL			247,383