

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5204	DATE	September 1, 2022
MANUFACTURER	KYOKUTO KAIHATSU KOGYO CO., LTD. 6-1-45, Koshienguchi, Nishinomiya-shi, Hyogo prefecture, Japan		
DESCRIPTION OF DEFECT	In some bulk tank trucks, due to improper installation of its rear combination lamps, the outermost position of its tail lamps may be more than 400mm from the outermost side of the trucks and shall not comply with the Japanese vehicle safety regulation which stipulates the aforesaid position shall be within 400mm.		

MANUFACTURER'S NAME	TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UD TRUCKS	2PG-CD4BA	QUON	2021-2022	7
	2PG-CD4CA		2022	2
	2PG-CD5BA		2022	1
	2PG-CD5BL		2022	3
	2PG-CD5CA		2021-2022	4
	2PG-CD5CL		2022	4
	2PG-CW5CA		2022	1
	2PG-CW5CL		2022	2
			TOTAL	24