

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|---|------|--------------------|
| CAMPAIGN No. | 5205 | DATE | September 16, 2022 |
| MANUFACTURER | YANMAR AGRIBUSINESS CO.,LTD. | | |
| DESCRIPTION OF DEFECT | In anagricultural tractor controller, ionic migration may occur due to inappropriate substrate protective materials. Therefore, if you continue to use it as it is, the controller will malfunction, and in the worst case, it will move forward or backward to brake operation, or it will not move forward or backward to reverser lever operation, or it will move in the direction opposite to the operation direction of the reverser lever, or the engine may stop and not restart. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE | |
|-----------|-----------------|---------------------|-------------------|--|
| - | 「EG224」 | 2007~2012 | 2,538 | |
| - | 「EG227」 | 2007~2012 | 2,278 | |
| | 「EG230」 | 2007~2012 | 1,425 | |
| - | 「EG221」 | 2012~2014 | 381 | |
| | | 2014~2015 | 246 | |
| | | 2014~2015 | 65 | |
| - | 「EG223」 | 2012~2014 | 445 | |
| | | 2014~2015 | 389 | |
| | 「EG225」 | 2012~2014 | 1,777 | |
| | | 2014~2015 | 1,537 | |
| | | 2014~2015 | 153 | |
| - | 「EG228」 | 2012~2013 | 897 | |
| | | 2014~2015 | 758 | |
| | 「EG231」 | 2012~2013 | 759 | |
| | | 2013~2015 | 633 | |
| | | 2013~2015 | 189 | |
| - | 「EG116」 | 2012~2017 | 90 | |
| | 「EG118」 | 2011~2012 | 186 | |
| | | 2012~2017 | 697 | |
| | 「EG120」 | 2011~2012 | 245 | |
| | | 2012~2017 | 923 | |
| | | 2012~2017 | 302 | |
| | | 2013~2017 | 202 | |
| | 「EG122」 | 2011~2012 | 111 | |
| 2012~2017 | | 295 | | |
| TOTAL | | | 17,521 | |