

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5206	DATE	Sep.20 2022
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some light-duty buses, a defective vehicle front side door latch assembly for the swing door may be installed due to improper manufacturing of the part. If the vehicle continues to be used in this condition, the latch may break and prevent the swing door from opening.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2RG-BE740E	「FUSO ROSA」	2022~2022	2
2RG-BE740G		2021~2022	22
2RG-BE740J		2022~2022	2
2RG-BG740G		2022~2022	4
		TOTAL	30

Vehicles which had the affected parts installed after they rolled off the assembly line.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KC-BE654G	「FUSO ROSA」	1997	1
KK-BE63EG		2001	1
PDG-BE66DG		2009	1
PDG-BG64DG		2009~2010	2
TPG-BE640G		2012~2012	2
		TOTAL	7