

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5207	DATE	Sep. 27. 2022
MANUFACTURER	Trantechs, Ltd.		
DESCRIPTION OF DEFECT	Due to improper design of the left front and rear wheel fender flaps of the large 4-axle truck, the fender flaps and the resin-made urea water tank continue to interfere with each other during driving. As a result, the urea water tank may be scraped by running vibration etc. In the worst case, the urea water tank may be punctured and the urea water may leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FS74GZ	FUSO Super Great	2018~2021	45
2PG-FS74HZ		2017~2022	96
2PG-FS75HZ		2018~2022	13
		TOTAL	154