

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5210	DATE	September. 30. 2022
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	On container carriers with a detachable container system, which are equipped with movable underrun protection device, the structure of underrun protection device is not appropriately designed, therefore crack may occur due to vibration and other factors while driving. If the operation under aforementioned state would continue, the location of underrun protection device changes and does not comply with the safety standards of road transport vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FE2ABA	RANGER	2021	2
2PG-GX2ABA		2022	1
2KG-FE2ACA		2022	1
2KG-FK72FZ	FIGHTER	2021~2022	2
2KG-FK72FY		2022	2
2RG-FTR90U2	FORWARD	2021~2022	3
		TOTAL	11