

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 2 1 4	DATE	Oct.06.2022
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the backdoor hinges, the fixing nut to body side may be tightened with over specified tightening torque due to inappropriate instrucion of operation and inspection in a manufacturing processes. Therefore, the fastening bolt may deform, and in the worst case, one side of the hinges may come off and it may not comply with the requirement for strengthen of vehicle prescribed in “Safety Regulations for Road Vehicles” , Article 18.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ZAA-ZE1	LEAF	2 0 2 2	1 0 8
		TOTAL	1 0 8