

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 2 2 4	DATE	Oct.27.2022
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the winding device (retractor) of the seat belt in the front seat, the front seatbelt occupant restraining performance (which keeps the restraint force of the seat belt stable) may degraded due to improper parts processing. Therefore, it may not satisfied with the the protective performance of the occupants in the event of an impact by a collision.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
4BA-R35	GT-R	2022	238
TOTAL			238

The affected parts shipped as repair parts.

PARTS NAME	PARTS NO.	DELIVERLY YEAR	QUANTITY
Driver/Passenger seat belt	86884-JF05A	2022	13
	86884-6HROA		
	86884-KC11A		
	86885-JF00A		
	86885-KC11A		
	86885-6HROA		
TOTAL			13