

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5228	DATE	October.31. 2022
MANUFACTURER	SHINMAYWA INDUSTRIES, LTD.		
DESCRIPTION OF DEFECT	<p>On vehicles equipped with hydraulically retractable rear underrun protection device for dump trucks, due to improper assembly procedures, there are such devices manufactured without fitting stopper plate which receives force of collision. When provided with a test load, the amount of deformation of the device exceeds standard and becomes non-conformant to safety regulations for road vehicles.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-CXZ77CT	GIGA	2022	3
2PG-CD5CL	QUON	2022	1
2PG-CW5AL		2022	1
		TOTAL	5