

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	5231	DATE	November 21. 2022
MANUFACTURE	Topre Corporation		
DESCRIPTION OF DEFECT	<p>In the mounting of the rivet cover on the corner rail of the cargo box of a large refrigerated vehicle, the amount of adhesive applied was inappropriate, and there was a case where the adhesion of the joint deteriorated due to insufficient fitting. Therefore, the rivet cover may swell due to vibration or the like during running, and in the worst case, the rivet cover may fall off. Inspect the rivet covers of all vehicles, and if there is no lift, rivet the rear end. If there is a lift, replace the rivet cover and rive the rear end.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-CVR60C	GIGA	2021	1
2KG-CXY77CJ		2018~2020	13
2KG-CYJ77C		2017~2021	162
2KG-CYJ77CA		2017~2021	111
2KG-CYL77C		2017~2021	61
2KG-CYL77CA		2018~2021	28
2KG-CYL77CZ		2017~2021	3
2KG-CYY77C		2018~2021	4
2KG-CYY77CY		2018~2021	71
2PG-CYJ77C		2017~2021	59
2PG-CYJ77CA		2017~2020	32
2PG-CYL77C		2018~2021	27
2PG-CYL77CA		2017~2021	7
2PG-CYL77CZ		2019~2021	4
2PG-CYY77C		2018~2020	2
2PG-CYY77CY		2018~2020	9
PDG-CYL77V8		2019	1
QKG-CXE77B		2017	4
QKG-CXJ77BA		2017	1
QKG-CXY77BJ		2017	10
QKG-CYJ77B		2017~2019	72
QKG-CYJ77BA		2017~2018	35
QKG-CYJ77BZ		2017	2
QKG-CYL77AZ		2017	1
QKG-CYL77B		2017	35
QKG-CYL77BA		2017	6
QKG-CYL77BZ		2017~2018	7
QKG-CYY77B		2017	2
QKG-CYY77BY		2017	17
QPG-CYJ77B		2017	4
QPG-CYL77B		2017	4
QPG-CYL77BA	2017	1	
2PG-FSR90T2	FORWARD	2020	1
SPG-FSR90T2		2017	2
2PG-FTR90V2		2018~2021	16

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-FVR90U2	FORWARD	2020	1	
2RG-FTR90V2		2018~2020	4	
LKG-FTR90T2		2017	6	
LPG-FTR90T2		2017	2	
QKG-FTR34T2		2017	2	
QKG-FVZ34U2		2017	1	
2KG-FR1EHG	HINOPROFIA	2020	1	
2KG-FW1EHG		2017~2021	7	
2PG-FH1AGA		2018	1	
2PG-FH1AGG		2021	1	
2PG-FN1AGG		2018	2	
2PG-FQ1AJG		2017~2021	26	
2PG-FQ1AJJ		2018~2020	19	
2PG-FR1AHG		2017~2021	30	
2PG-FR1AHJ		2017~2021	28	
2PG-FR1EHG		2019~2020	5	
2PG-FR1EHJ		2018~2020	5	
2PG-FS1AHG		2018~2020	5	
2PG-FS1AHJ		2017~2020	6	
2PG-FW1AHG		2017~2021	157	
2PG-FW1AHJ		2017~2021	86	
2PG-FW1AJG		2017~2020	2	
2PG-FW1AJJ		2018~2020	4	
2PG-FW1EHG		2018~2020	10	
2PG-FW1EHJ		2020	1	
2RG-FR1AHG		2017~2021	23	
2RG-FR1AHJ		2018~2020	10	
2RG-FW1AHG		2017~2021	35	
2RG-FW1AHJ		2017~2021	37	
BKG-FW1EXYJ		2019	1	
LKG-FW1EXBJ		2019	1	
PK-FR1EXWG		2019	1	
QKG-FE7JPAG		2017	1	
QKG-FE7JUAG		2017	3	
QKG-FW1EXEG		2017	2	
QPG-FQ1EWEG		2017	7	
QPG-FQ1EWEJ		2017	5	
QPG-FR1EXEG		2017	6	
QPG-FR1EXEJ		2017	11	
QPG-FW1EXEG		2017	35	
QPG-FW1EXEJ		2017~2018	23	
QPG-FW1EYEG		2017	5	
QPG-FW1EYEJ		2017	1	
QPG-FW1EZEG		2017	1	
2DG-GK2ABA		HINORANGER	2018~2019	5
2KG-FE2ABG			2019	1
2KG-GD2ABG	2019		4	
2PG-FE2ABG		2018~2021	15	
2PG-FS74GY	FUSOSUPERGREAT	2018~2021	8	
2PG-FS74GZ		2020	3	
2PG-FS74HY		2017~2018	3	
2PG-FS74HZ		2017~2021	169	
2PG-FS75HZ		2017~2021	80	
2PG-FU74HZ		2017~2021	51	
2PG-FU75HZ		2017~2021	15	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
2PG-FV74HZ	FUSOSUPERGREAT	2019~2021	5	
2PG-FY74HY		2017~2021	19	
QPG-FS64VZ		2017~2018	28	
QPG-FS65VZ		2017	10	
QPG-FU64VY		2017	1	
QPG-FU64VZ		2017~2018	10	
QPG-FU65VZ		2017	3	
QPG-FY64VY		2017	3	
QDG-FQ62F		FUSOFIGHTER	2017	1
2PG-CD5BA	QUON	2018~2020	4	
2PG-CD5CA		2017~2021	39	
2PG-CD5CE		2019~2020	14	
2PG-CG5BA		2018	3	
2PG-CG5CA		2017~2021	64	
2PG-CG5CE		2018~2021	35	
2PG-CW5CA		2019	1	
2PG-CX5BA		2018	1	
LKG-CD5ZA		2020	1	
QPG-CD5ZA		2017	7	
QPG-CD5ZE		2017	7	
QPG-CG5YA		2017	1	
QPG-CG5ZA		2017~2018	12	
QPG-CG5ZE		2017	2	
2RG-BSR90T2		CONDOR	2020	1
			TOTAL	2,061