

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	5236	DATE	Nov. 24. 2022
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	Regarding the recall No. 5157 filed on June 2, 2022, a wrong fixing clip has been attached to the battery cable in question due to an inappropriate description in the manual for inspecting and replacing the cable. If used as is, the coating of the said cable may be worn due to engine vibration, and consequently the strands may be exposed and short-circuited. In the worst case, the engine may not start.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-KR290J4	[HINO Rainbow]	2021	14
2KG-KV290N3	[HINO BlueRibbon]	2021	3
2RG-KV290Q3		2021~2022	3
2TG-KV290Q3			
		TOTAL	20