

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 2 4 0	DATE	Dec. 1. 2022
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>In the lithium-ion battery internal fuse for NISMO-S spec vehicles, the fuse deterioration may be accelerated early depending on the specific driving condition due to the improper specification setting of the fuse.</p> <p>If you continue to drive in this condition, in the worst case, the fuse may be blown and the warning lamp may illuminate, and the power supply to the motor may be cut off and the vehicle may not be driven.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HE12	NOTE	2018 ~ 2020	4,856
		TOTAL	4,856