

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

|                       |  |      |           |
|-----------------------|--|------|-----------|
| CAMPAIGN No.          | 5233   | DATE | 2022/12/8 |
| MANUFACTURER          | YANMAR CONSTRUCTION EQUIPMENT CO. , LTD.   |      |           |
| DESCRIPTION OF DEFECT | There is no enough clearance between the hydraulic hose and the frame on the shovel loader since the drawing direction was not proper. There is a fear that the hose and the frame will interfere by vibration and the hose will be broken then the hydraulic oil will leak. Traveling could be malfunction in the worst case. |      |           |

| TYPE  | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-------|-----------------|---------------------|-------------------|
| L2DA  | V2-3B           | 2020 to 2022        | 87                |
| WA117 | WA20-6          | 2020 to 2022        | 92                |
| TOTAL |                 |                     | 179               |

(日本工業規格A列4番)