

VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	5257	DATE	December 8, 2022
MANUFACTURER	Komatsu Ltd.		
DESCRIPTION OF DEFECT	In the shovel loader, due to improper assembly of the heating element of the fuel filter with heater, the heating element may tilt and come into contact with the clear bowl. Therefore, if customer continue to use it, the heat from the heating element will deform the clear bowl, and in the worst case, the clear bowl will be perforated, leading to fuel leakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
WDP-WA124	「WA100-7」	2017-2017	73
YDP-WA138	「WA100-8」	2018-2022	617
YDP-WA138	「WA150-8」	2020-2022	194
YDP-WR005	「WR12-8」	2021	1
YDR-WA137	「WA200-8」	2019-2021	85
YDR-WA136	「WA270-8」	2018-2019	2
TOTAL			972