

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5253	DATE	Dec. 9, 2022
MANUFACTURER	Kawasaki Motors, Ltd.		
DESCRIPTION OF DEFECT	An improper control program in Multi-function meter may cause the display to restart unexpectedly during use. If this occurs the rider would not be able to see the vehicle speed during use.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	Notes
8BL-ZXT02P	Ninja H2 SX Ninja H2 SX SE	2022	707	
TOTAL			707	