

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5262	DATE	2022/12/21
MANUFACTURER	TOHO CAR CORPORATION		
DESCRIPTION OF DEFECT	In a trailer with a lift axle function, the pressure value for starting the lifting and lowering motion of the lift axle was incorrectly set, which may cause the non-lift axle to exceed the allowable axle load of the safety standards of the Road Transport Vehicle Law.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TF28H8C21	wing van semi-trailer	2022	1
DNPTE241A	wing van semi-trailer	2021 ~ 2022	3
2 types in total	2 models in total	Overall range of production period 2021 ~ 2022	4