VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN


Domestic Import Vehicles

CAMPAIGN No.		DATE	December 19,2022		
MANUFACTURE	Lukura Co.,Ltd.				
	(Japanese Importer : Lukura Co.,Ltd.)				
DESCRIPTION OF DEFECT	Due to improper structural strength design in the vehicle frame, there are places where the strength of the vehicle frame is insufficient. Therefore, cracks and deformation may occur due to the load during running, and in the worst case, running performance may be lost and running may become impossible.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LIB5700B	-	2015-2021	59
LIB5700B2	-	2021-2022	17
LIB8260B	-	2016-2022	90
LIB11000B	-	2016-2022	191
		TOTAL	357

【記入例】

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN



TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
		製作年のみの記載。	
		TOTAL	

Domestic Vehicles:日本国内車両

Import Vehicles:輸入車両 CAMPAIGN No.:届出番号

DATE: 届出年月日

MANUFACTURE: 製作者名

DESCRIPTION OF DEFECT:不適合状態

TYPE:型式

COMMERCIAL NAME: 通称名

MODEL YEAR RECALLED:対象車両の製作年

NUMBER OF VEHICLE:対象車両数