

VEHICLE SAFETY RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5264	DATE	Dec. 23, 2022
MANUFACTURER	SUZUKI MOTOR CORPORATION		
DESCRIPTION OF DEFECT	<p>The back-up power supply capacitor in the air bag controller may have internal short circuit, due to the manufacturing failure.</p> <p>Due to the above, all of the air bags and the seat belt pre-tensioners may fail to activate in the vehicle collision event, if the power supply of the controller is cut off by the collision impact.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
5BA-MA27S	SOLIO	2022	459	
5AA-MA37S			4,174	
5BA-MX81S	WAGONR SMILE		390	
5AA-MX91S			3,026	
3BA-HA37S	ALTO		1,621	
5AA-HA97S			1,007	
4AA-MR52S	HUSTLER		1,485	
5AA-MR92S			4,048	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	NOTE
3BA-HB37S	CAROL	2022	174	
5AA-HB97S			108	
4AA-MS52S	FLAIR CROSSOVER		98	
5AA-MS92S			298	
5AA-MB37S	DELICA D:2		418	
			TOTAL	17,306