

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5 2 6 9	DATE	Jan. 27. 2023
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	In the ECO motor for smart simple hybrid vehicle with Idling Stop system, due to inappropriate seal specification of bearing in the unit, it may be broken with contamination which coming into bearing, and it may make the abnormal noise. If continue to be driven on this condition, in worst case, the engine may be stalled due to ECO motor breakage.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HC26	N I S S A N S E R E N A	2 0 1 2 ~ 2 0 1 6	6 1, 4 3 4
DAA-HFC26			1 8 5, 3 9 9
DAA-SHC26	S U Z U K I L A N D Y	2 0 1 2 ~ 2 0 1 6	3, 1 9 6
		TOTAL	2 5 0, 0 2 9