

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5270	DATE	February 2, 2023
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	In the air bag computer, an internal short circuit may occur due to the improper manufacturing process of the capacitor. Therefore, if the air bag computer is continuously used as it is, there is a risk that the air bag and the seat belt pretensioner will not operate at the time of the collision in which the air bag and the seat belt pretensioner are supposed to operate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5BA-LA650S	TANTO	2022	12,275
5BA-LA660S			3,163
5BA-LA900S	TAFT		4,460
5BA-LA910S			1,050
5BA-LA850S	MOVE CANBUS		5,479
5BA-LA860S			1,303
5BA-A201S	ROCKY		278
5AA-A202S			909
3BA-A210S			195
5BA-LA650F	CHIFFON		195
5BA-LA660F			66
5BA-A201F	REX		212
5BA-A201A	RAIZE		763
5AA-A202A			1,750
3BA-A210A			341
			TOTAL