

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5272	DATE	Feb.2.2023
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the plug-in hybrid system, due to an improper programming for the charge and discharge control of the battery, there is a possibility that when the hybrid battery voltage decreases by continuously using in EV mode, if the vehicle is rapid acceleration, the battery voltage drops more than expected. If this occurs, the warning lights will illuminate and the hybrid system will shut down.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6LA-AXAP54	[RAV4 PHV]	2020-2021	2,481
		TOTAL	2,481